FIG.I




FIG.2




FIG. 3



FIG.4




FIG.5









FIG.6
























09 48 FIG. 34 +40






FIG.38




FIG.39

124

142

134

166

120

128

136

130

144

FIG.40




FIG.41




FIG.42




FIG.43




FIG.44




FIG.45




FIG.46




FIG.47




FIG.48




FIG.49

116




FIG.50








FIG. 51




#### FIG.52A

















FIG.52F



















# FIG. 55 FIG. 56 212 FIG. 57 202-201 210 FIG.58A 210 FIG.58B **EXTERIOR** 218 INTERIOR

210

<sup>(</sup>201








FIG. 59




FIG. 60A




FIG. 60B




FIG.60C




FIG.60D




FIG. 60E




FIG.60F




FIG. 60G




FIG.60H









FIG. 601
















## FIG.62A



### FIG.62B



## FIG.62C




FIG. 62D







FIG. 62 E


CLAMPING MEMBER
FLEXES


HANDLE
MOTION
















FIG. 68











FIG. 73


FIG 74







F16.77









FIG. 78




F16.79



F16, 80



F16.81



F16.82







FIG 83







FIB. 85

FIG 86




FIG. . 87







FIG. 88








X





F16 91















F16.96



F16.97







F16.100

